
# MATERIAL SAFETY DATA SHEET

(DEW BREAK)



### PRODUCT DESCRIPTION

**SECTION 1.** 

MATERIAL IDENTIFICATION

#### Our Grating and frame are functional, attractive and economical solution to exterior and interior drainage problem provides

a dynamic and contemporary appearance to complement today's architectural spaces. MATERIAL USED

SAKSHI INNOVATIONS PRIVATE LIMITED

BRASS: Brass is an alloy made primarily of copper and zinc.

MANUFACTURER'S NAME

### Gurudwara Somasar Road, P.O. Sahnewal, Village TIBBA, Distt. LUDHIANA-141 120 (INDIA)

**SECTION 2.** COMPOSITION / INFORMATION ON INGREDIENTS

CAS No.

7440-66-6

% Weight

0.0038

36.49

Dust and fumes can cause irritation to the skin with itching, dermatitis may occur.

COPPER & ZINC (as Oxide): Inhalation overexposure to copper or zinc oxide may cause metal fume fever characterized by fever and chills (i.e. flu-like symptoms)

Chronic exposures may cause lead poisoning that can affect the digestive system, nervous system, reproductive systems, muscles and joints. IARC lists lead and its

Inhalation overexposures may cause a benign pneumoconiosis (stannosis) with

Maintain good personal hygiene. Wash affected area with mild soap and water.

Remove to fresh air, breathing and presence of pulse. If necessary consult a

Rare in industry. Dust may irritate mouth and gastrointestinal tract. If ingested,

Not applicable for solid product. Use extinguishers appropriate for surrounding

Operations with the potential for generating high concentrations of airborne particulates should be evaluated and controlled as necessary. Practice good

Use controls as appropriate to minimize exposure to metal fumes and dusts

Provide general or local exhaust ventilation systems to minimize airborne concentrations. Local exhaust ventilation is preferred because it prevents contamination dispersion into the work area by controlling it at its source.

Seek professional advice prior to respirator selection and use. Follow OSHA

Use protective clothing, gloves and safety glasses or goggles as required for welding, burning, sawing, brazing, grinding or machining operations. Do not

Under normal conditions of storage and use, hazardous reactions will Not Occur.

respirator regulations (29 CFR 1910.134) and, if necessary, wear a NIOSH-approved respirator. Select respirator based on its suitability to provide adequate worker

Respiratory system, kidney, liver, central nervous system, eyes and skin.

#### Chemical Composition Carbon 7440-44-0 Zinc

| <b>■</b> Iron          | 7439-89-6         | 0.034  |
|------------------------|-------------------|--------|
| Manganese              | <i>7</i> 439-96-5 | 0.0033 |
| Phosphorus             | <i>77</i> 23-14-0 | 0.0014 |
| Silicon                | 7440-21-3         | 0.003  |
| ■ Sulphur              | 7704-34-9         | 0.003  |
| ■ Nickel               | 7440-02-0         | 0.006  |
| <b>■</b> Lead          | 7439-92-1         | 0.02   |
| Aluminium              | <i>7</i> 429-90-5 | 0.0045 |
| <b>■</b> Beryllium     | 7440-41-7         | 0.007  |
| Copper                 | 7440-50-8         | 63.40  |
| ■ Silver               | 7440-22-4         | 0.005  |
| <b>■</b> Bismuth       | 7440-69-9         | 0.0046 |
| <b>■</b> Tin           | <i>7</i> 440-31-5 | 0.0014 |
| Antimony               | 7440-36-0         | 0.010  |
| Arsenic                | 7440-38-2         | 0.003  |
|                        |                   |        |
| HAZARDS IDENTIFICATION |                   |        |

## operations may generates dusts, fumes and machine turnings that may create a health or fire or explosion hazard.

SECTION 3.

TARGET ORGANS

TO MATERIAL

LEAD

TIN

SKIN

INHALATION

**INGESTION** 

SECTION 5.

FLAMMABILITY CLASSIFICATION

MEANS OF EXTINCTION

SPECIAL FIRE FIGHTING

HANDLING PRECAUTIONS

**ENGINEERING CONTROLS** 

RESPIRATORY PROTECTION

PROTECTIVE CLOTHING/EQUIPMENT

**VENTILATION** 

SECTION 9.

DENSITYG/CM3

HARDNESS (HV5)

SECTION 10.

SECTION 11.

SECTION 12.

DISPOSAL

**OSHA REGULATIONS** 

REMARKS

SECTION 16.

POSSIBILITY OF HAZARDOUS

STABILITY

SECTION 4.

EFFECTS OF ACUTE EXPOSURE

**ROUTES OF ENTRY:** None in its solid state .High concentrations of dust and fumes may cause irritation to the eyes. Inhalation of metal fumes and dusts generated during welding, burning, grinding or machining may cause irritations of the respiratory tract. Flu-like symptoms such as fever and chills may occur a few hours after excessive exposure.

Brass allous in their usual form and under normal conditions do not present an inhalation, ingestion or contact health hazard or fire or explosion hazard. Operations such as welding, brazing, burning, grinding, cutting, heat treating, machining or similar

which appear 4-6 hours after exposure with no longterm effects.

EFFECTS OF CHRONIC EXPOSURE TO MATERIAL

inorganic compounds under its Group 2B category -

few or no symptoms, which is reported not to be disabling.

"possibly carcinogenic to humans".

FIRST AIDS MEASURES

**EYES** Flush eyes with plenty of water for at least 15 min, holding eyes lids open. Seek medical attention if eyes irritation persist.

Seek medical attention if eyes irritation persist.

seek medical attention promptly. FIRE FIGHTING MEASURES

Non-flammable. Will not support combustion.

physician immediately.

HAZARDOUS COMBUSTION PRODUCTS At temperatures above the melting point, fumes containing metal oxides and other alloying elements may be liberated.

UNUSUAL FIRE HAZARDS Finely divided particles or dusts such as those produced during grinding may present an explosion hazard, and should be treated as a Class D combustible metal fire - use a use Class D fire extinguishers (dry powder or sand) for fires

involving powders or dusts.

materials.

SECTION 6. ACCIDENTAL RELEASE MEASURES Minimal problems with spills of this product would be expected to occur because of its solid form.

Do not use water on molten metal.

#### housekeeping. Avoid breathing metal fume and/or dust. STORAGE REQUIREMENTS Store away from acids and incompatible materials.

**SECTION 7. HANDELING & STORAGE** 

**EXPOSURE CONTROLS/ PERSONAL PROTECTIONS** SECTION 8.

during handling operations.

### ADMINISTRATIVE CONTROLS Do not use compressed air to clean-up spills.

protection for given working conditions, level of airborne contamination, and presence of sufficient oxygen.

continue to use gloves or work clothing that has become saturated or soaked through with oil coating. Wash skin that has been exposed to oil with soap and water or waterless hand cleaner. PHYSICAL PROPERTIES OF FLOOR GRATING WITH FRAME

# **REACTIONS**

8.5

135

**REACTIVITY AND STABILITY** 

TOXICOLOGICAL INFORMATION

**ECHOLOGICAL INFORMATION** 

According to our experience and information the product has no harmful effects on health if properly handled.

properly handled.

The product is stable.

### **DISPOSAL CONSIDERATIONS** SECTION 13.

environmental professional and disposed of in accordance with applicable Federal, state or local regulations.

Material is not listed as a hazardous substance for any mode of transportation.

Brass scrap should be recycled whenever possible. Product dusts and fumes from processing operations should also be recycled, or classified by a competent

The product is practically insoluble in water. In views of its consistency and insolubility in water, no ecological Problems are to be expected if the product is

### CONTAINER CLEANING AND DISPOSAL : Follow applicable Federal, state or local regulations. Observe safe handling

SECTION 14. TRANSPORT INFORMATION

#### SECTION 15. **REGULATORY INFORMATION**

: The product as a whole is not listed. However, individual components of the product are listed.

Product is in compliance with substance of Very High Concern (SVHC)

# i.e. ≤ 0.1 %w/w as per the candidate list promulgated by the European Chemicals

OTHER INFORMATION

Agency (ECHA) which are defined in Article 57 of REACH Regulation (EC1907/2006) checked by Tuv-Nord Group.

**DISCLAIMER** The data contained herein is based on information that SAKSHI INNOVATIONS PVT. LTD. believes to be reliable,

a given situation.

# but no expressed or implied warranty is made with regard to the accuracy of such data or its suitability for